



SECTION 1

SECTION 1



## **PRODUCT QUALITY / SERVICE UPDATE**

TO: All Locations  
FROM: TONY RIVERA  
Leisure Bay Manufacturing  
December 8, 2005

### **WATER IN STEREO CD PLAYER OR REMOTE**

**PRODUCT AFFECTED:** All imperial plus model spas.

**SITUATION REPORTED:** CD player/radio and or remote stop working and in most cases, water condensation was discovered inside of digital display.

**CORRECTIVE ACTION:** We have switched to Gecko brand stereos.



Old Stereo System



New Stereo System

**FIELD SERVICE RECOMMENDATION:** Replace the Magnadyne stereo with the new Gecko brand. A retrofit kit is available to replace the defective Magnadyne stereo. The kit includes a Gecko stereo/CD player, remote, cabinet trim, illustrated instructions, and special tools. The kit can be ordered through our parts and service department. The part numbers are **303465C for Cherry** or **303465G for Cherry Gray** cabinet panels.